

: SMALL /MED FAB

User.

Tuesday, 15/07/2008 4:19:52 PM

Julie Lecocq

Process Sheet

: CU-DAR001 Dart Helicopters Services Customer

Job Number : 40530 : 12782 **Estimate Number**

P.O. Number

This Issue

: 15/07/2008 Prsht Rev. : NC

First Issue : 11

: 33801 Previous Run

Written By

Checked & Approved By

Comment

: Est Rev:A New Issue 07-03-08 ec

S.O. No. :

Type

As per Rev C 07-07-09 JLM Est Rev:B

Est Rev:C

As per Rev D 07-09-09 JLM Verified By:EC

Drawing Name

: WEARPAD

Part Number

Drawing Number

: D35643 . D3564 REV D

Project Number : N/A : D **Drawing Revision**

Material

: 05/08/2008 **Due Date**

Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

2.0

M304S16GA

WATER JET

Comment: FLOW WATER JET

304/316 .063 Sheet

Comment: Qty.: 1.1550 sf(s)/Unit Total: 23.1000 sf(s)

M304S16GA Stainless steel sheet 0.063" thick

108774 Batch:

FLOW WATER JET



1-Cut as per Dwg D3564

Dwg Rev: D

Prog Rev: 0

76-F-8 A

*****(D3564-1F)*****

2-Deburr if necessary

B 8-7-36

3.0 QC2

INSPECT PARTS AS THEY COME OFF MACHINE



13 8-7-25

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

QC8

Comment: SECOND CHECK

BRAKE NO

NC BRAKE

SECOND CHECK

Comment: NC BRAKE

Deburr if necessary

Form on Brake as per Dwg D3564 using Jigs DT8179 and DT8155

Dart Aerospace Ltd

Duitrio									
W/O:	3 1140		W	ORK ORDER CHANGE	S			,	
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
								e'	
			ž.						
Part No		PAR #:	Fault Cat	egory:				Date:	
NCR:		W	ORK ORI	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign Date			Approval Chief Eng	Approval QC Inspector
		3							

NOTE: Date & initial all entries

 Tuesday, 15/07/2008 4:19:52 PM Date: User: Julie Lecocq **Process Sheet** Drawing Name: WEARPAD Customer: CU-DAR001 Dart Helicopters Services Job Number: 40530 Part Number: D35643 Job Number: Seq. #: Machine Or Operation: Description: Form Joggle as per Dwg D3564 on brake using Jig DT8157 QC5 INSPECT WORK TO CURRENT STEP 6.0 WORK TO CURRENT STEP Comment: INSPEC Ensure joggle as per dwg D3429 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 7.0 Comment: LARGE FABRICATION RESOURCE 1 Batch Qty Description 9108631 2059B Hardcoat Weld hardcoat as per Dwg D3437 QC10 VISUAL INSPECTION OF GROUND WELDS 8.0 INSPECTION OF GROUND WELDS Comment: VISUAL QC5 INSPECT WORK TO CURRENT STEP 9.0 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 10.0 106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref. 4.3.5.6) as per QSI 005 4.3 START TIME: OVEN TEMPERATURE: FINISH TIME: INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:

Dart Aerospace Ltd

W/O:		The state of the s	V	VORK ORDER CHANG	ES					
DATE	STEP	PROC	EDURE CH	HANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	au au pri									3
* W										
										0.49
i de la la										
Part No:		PAR #:	_ Fault Ca	tegory:	NCR	: Yes N	o DQA	٨:	_ Date: _	
						QA: N/0	Closed	l:	_ Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE	(NCR)				
DATE	STEP	Description of NC		Corrective Action Section	on B		Verific	ation	Approval A	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
>-										
1 1										. 4
										7
		7-								
	199									

NOTE: Date & initial all entries

Date: User: Tuesday, 15/07/2008 4:19:52 PM

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPAD

Job Number: 40530

Part Number: D35643

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE



Doelselo

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




MF 08.08-0


Dart Aerospace Ltd

Daitrio	JOP CO.								
W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHAP	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
2									3.00
Part No:		PAR #:	Fault Categ	Jory:	NCR: Yes	No DQA	ı:	_ Date: _	
						N/C Closed	l:	_ Date: _	
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (NC	R)			1, -2% M
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	A STATE OF THE STA	Sign & Verifica		Approval	Approval
		Section A	Chief Eng	Chief Eng	Date		n C	Chief Eng	QC Inspector
									3


NOTE: Date & initial all entries



ALLE OF DESIGNATION OF THE PROPERTY OF THE PRO



MOSK OSCIER MARKOLOSTICK SIUTBOLLOSTICKE BROKESTICKE FROMESTICKE THOMASTICKE T



-DART-AEROSPACE LTD	Work Order:	40(30
Description: WEAR PAD	Part Number:	D 3664-3
Inspection Dwg: 03(64/3 Rev:		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article	Prototype	9

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.227	4/010	3:226				
2.432	+/010	2,435				
2,56	+/030	2.563				
6.006	4/016	6.000			22	
12.104	1/2 .010	12.104				
18.000	010	18.000				
18.000	010	18.000				
18.00	4- 1030	18.00				
9.00	+/030	9.06				
11.50	4/030	11.50				
300 x 300	1/- ,010	304 x, 304				
Ø .188	10054.001	. 192				
R .375	4/010	,375				
.663		,061				

Measured by:	HB	Audited by:	5	Prototype Approval:	1	
Date:	8-7-05	Date:	08/07/85	Date:		9

1	Rev	Date	Change	Revised by	Approved
	Α		New Issue	KJ/JLM	

